



Permanent Magnet

1 pole pair



Electrical Machine with two pole pairs ($p=2$)




The colors (red/blue) correspond to how field lines are colored in ONELAB models of machines

$$s = \frac{\frac{\omega}{p} - \dot{\theta}}{\frac{\omega}{p}}$$

$\frac{\omega}{p} \equiv$ synchronous speed

$$\dot{\theta} = (1-s) \frac{\omega}{p}$$



Ex $\frac{\omega}{p} = 1500 \text{ rpm} \quad (50 \text{ Hz } p=2)$

$$\dot{\theta} = 1440 \text{ rpm}$$

$$s = \frac{1500 - 1440}{1500} = 4\% = 0.04$$

Slide 3

$$\begin{aligned}\bar{E}_1 &= -j\omega h_1 \bar{\Phi}_1 \\ &= -j\omega h_1 \left(-\frac{h_1' \bar{I}_1 + h_2' \bar{I}_2}{\mathcal{R}} \right) \quad \mathcal{R} \equiv R_{ep}\end{aligned}$$

$$= j\omega \frac{h_1 h_1'}{\mathcal{R}} \bar{I}_1 - j\omega \frac{h_1 h_2'}{\mathcal{R}} \bar{I}_2'$$

$$= j\omega \frac{h_1 h_1'}{\mathcal{R}} \left(\bar{I}_1 - \frac{h_2'}{h_1'} \bar{I}_2' \right)$$

$$= j\omega X_m \left(\bar{I}_1 - \frac{\bar{I}_2}{m_{12}} \right)$$

$$m_{12} = \frac{h_1'}{h_2'}$$

$$X_m = \frac{h_1 h_1'}{\mathcal{R}}$$

$$\bar{E}_1 = j\omega X_m \left(\bar{I}_1 - \bar{I}_2' \right)$$


$$\bar{I}_2' = \frac{\bar{I}_2}{m_{12}}$$

$$= j\omega X_m \bar{I}_m$$

The phasor algebra for the asynchronous machine is thus very similar to that of the transformer.

Slide 5

Per Phase

Realistic values

$$X_m = 20 \Omega \quad R_1 = 0.1 \Omega \quad R_{H+F} = 800 \Omega \quad X_1 = 0.5 \Omega$$


No Load $Z_{TOT} = R_1 + jX_1 + \left(\frac{1}{jX_m} + \frac{1}{R_{H+F}} \right)^{-1}$

which is too complicated already for a "mental picture" model. But one notices that

$$Z_{TOT} \approx jX_m \Rightarrow \bar{I}_1 = \frac{\bar{U}_1}{jX_m}$$

$$\Rightarrow I_1 \approx \frac{220V}{20\Omega} = 11A$$

$$\Rightarrow \bar{E}_1 = \bar{U}_1 - (R_1 + jX_1) \bar{I}_1$$



$$U_1 = 220V \quad E_1 = 214V \approx U_1$$

This example intends to show how good/bad are the approximations done routinely in this course.

Slide 8 : Stable and unstable zone



$$\frac{\partial C_{us}}{\partial \delta_m} < 0 \Rightarrow \text{Stability}$$

(C_f synchronous machine
Slide 14)

$$\frac{\partial C_{motor}}{\partial \dot{\theta}} < 0 \Rightarrow \text{Stability}$$

$$\dot{\theta} = (1-g) \frac{\omega}{p}$$

$$\frac{\partial C_{motor}}{\partial g} > 0 \Rightarrow \text{Stability}$$



Flux

$$\phi_m = \frac{1}{\mu} I_m = \frac{X_m I_m}{\omega} = \frac{E_1}{\omega} \approx \frac{U_1}{\omega}$$

- * In an induction motor connected to the net ($U_1 = \text{cst}$, $\omega = \text{cst}$) the flux is always the same, whatever the load.
- * The flux is also constant if the ratio U_1/ω is maintained constant (e.g. for speed control, slide 9)

Active power (slide 6)

$$\frac{C \omega}{P}$$

$$P = 3 U_1 I_1 \cos \varphi = P_{J \text{ stator}} + P_{\text{stator} \rightarrow \text{rotor}}$$


$$= 3 \left(R_1 I_1^2 + \frac{R_2'}{g} I_2'^2 \right)$$

$$P = P_{J \text{ stator}} + P_{J \text{ rotor}} + \overbrace{P_{\text{elm}}}^{\text{co}}$$


$$= 3 \left(R_1 I_1^2 + R_2' I_2'^2 + R_2' \left(\frac{1-g}{g} \right) I_2'^2 \right)$$

Start up (slide 10)

$$C_{\text{motor}} - C_{\text{res}}(\dot{\theta}) = I \ddot{\theta} \quad I = \text{inertia}$$




- ⊕ $C_{\text{motor}} \leq C_{\text{load}} \Rightarrow C_{\text{res}}(\dot{\theta}=0) = C_{\text{motor}} = I \ddot{\theta} = 0$
The motor does not start



- A $C_{\text{motor}} > C_{\text{load}} \Rightarrow I \ddot{\theta} > 0 \Rightarrow$ the motor starts
 $\dot{\theta}$ increases, g decreases

- B $C_{\text{motor}} - C_{\text{load}}$ is maximum.
acceleration $\ddot{\theta}$ is maximum

- C $C_{\text{motor}} = C_{\text{load}} \Rightarrow$ stable equilibrium point




Two contradictory conditions for the start-up of the induction motor

- limit the start-up current

$$I_d = \frac{U_1}{\sqrt{(R_1 + R_2')^2 + (X_1 + X_2')^2}}$$

- have a sufficiently large start-up torque



- does not start
- I_d very large


- ⊕ With a normal squirrel cage motor, no action is possible at the rotor. The best one can do is to start in star connection
- Start-up torque divided by 3
 - Start-up phase current $\frac{\sqrt{3}}{3}$
- and then to switch in Δ (slide 10)

⑦ With a wound rotor
(rotor of a synchronous machine with short-circuited rings)

Here the solution is to insert resistances R_{st} in series with the rotor windings

$$\frac{T_d(R_{st})}{T_d(R_{st}=0)} = \frac{U_1}{\sqrt{(R_1 + R_2' + R_{st})^2 + (X_1 + X_2')^2}} \ll \frac{T_d(R_{st}=0)}{T_d(R_{st}=0)}$$

and to remove them progressively



But we do not want rings and tedious connection mechanisms

→ clever squirrel cage rotor

Slide 11

$$C_{\text{start}} = \frac{3p}{\omega} R_2' \frac{U_1^2}{R_2'^2 + X_2'^2} \approx \frac{3p}{\omega} R_2' \frac{U_1^2}{X_2'^2}$$


is proportional to R_2'

$$\text{Slope } \partial_g C(g=0) = \frac{3p}{\omega} \frac{U_1^2}{R_2'}$$

is inversely proportional to R_2'

Double cage

regime ($g \ll 1$) Startup ($g=1$)



At start up, $R_e' \gg R_1'$ but $X_1' \gg X_e'$

ensure that I_e' is not $\ll I_1'$, i.e., $I_e' \approx I_1'$

In regime, $\frac{R_e'}{g} \gg \frac{R_1'}{g} \gg X_1' \gg X_e'$ and $I_1' \gg I_e'$

Speed Control (slide 3)

Speed control means

How can one modify the rotation speed ω corresponding to a given resistant torque (load) C_{res} ?

With

- modification of R_2'
- U_1

one buys a bad / limited speed control with a significant loss of efficiency

The good way to control speed is to modify V_1 and ω so as to maintain the ratio V_1/ω constant, i.e. constant flux in the machine. Power electronics is needed for that.

$$\textcircled{*} C_{max} = \frac{3P}{\omega} \frac{V_1^2}{2X_2'} \quad (\text{cf slide 7})$$

$$= \frac{3P}{\omega} \frac{V_1^2}{2\omega L_2'} = \frac{3P}{2L_2'} \left(\frac{V_1}{\omega} \right)^2$$

remains constant all speeds

$$\textcircled{*} \frac{\partial C}{\partial g}(g=0) = \frac{\partial C}{\partial g}(g=0) \frac{\partial g}{\partial \omega} \quad g = 1 - \frac{\omega}{\omega'}$$

$$= \frac{C_{ge}}{g} (\text{slide 7}) \frac{\partial g}{\partial \omega}$$

$$= \frac{3P}{\omega} \frac{V_1^2}{R_2'} \left(-\frac{P}{\omega} \right) = -\frac{3P^2}{R_2'} \left(\frac{V_1}{\omega} \right)^2$$

remains constant at all speeds

$\textcircled{*}$ The slips corresponding to C_{max} is

$$g_{max} = \pm \frac{R_2'}{X_2'} \quad (\text{slide 7})$$

$$\omega_{max} = (1 - g_{max}) \frac{\omega}{P} = \left(1 \mp \frac{R_2'}{X_2'} \right) \frac{\omega}{P}$$

$$= \frac{\omega}{P} \mp \frac{R_2'}{P L_2'}$$

$\underbrace{\hspace{1cm}}_{\text{constant for all speeds}}$

Slide 12: Circle diagram

$$\textcircled{*} P = 3U_1 I_1 \cos \varphi = 3U_1 AM \Rightarrow AM = \frac{P}{3U_1}$$

$$\textcircled{*} Q = 3U_1 I_1 \sin \varphi = 3U_1 (O'D + OA)$$

$$= Q_{X_m} + Q_X = 3X_m I_m^2 + 3X I_2'^2$$

$$\Rightarrow 3U_1 OA = 3X I_2'^2 \Rightarrow OA = \frac{X I_2'^2}{U_1}$$

$$\textcircled{*} \bar{U}_1 = jX \bar{I}_2' + \left(R_1 + \frac{R_2'}{g} \right) \bar{I}_2'$$

$$\Rightarrow \frac{\bar{U}_1}{jX} = \bar{I}_2' + \frac{R_1 + \frac{R_2'}{g}}{X} \bar{I}_2'$$

The constant phasor $\frac{\bar{U}_1}{jX}$ is the sum of two orthogonal phasors

$\Rightarrow$ the locus of the tip of $\bar{I}_2'$ is a circle of diameter $\frac{U_1}{X}$

$$\textcircled{*} P_{JS} = 3 R_1 I_1^2 \approx 3 R_1 I_2'^2 \text{ with } I_2'^2 = \frac{U_1}{X} OA$$

$$= 3 R_1 \frac{U_1}{X} OA$$

$$\Rightarrow \frac{P_{JS}}{3U_1} = \frac{R_1}{X} OA = AB$$

is thus represented by a straight line starting from 0 and with slope $\frac{R_1}{X}$

$$\textcircled{*} P_{JR} = 3 R_2' I_2'^2 = 3 R_2' \frac{U_1}{X} OA$$

$$\Rightarrow \frac{P_{JR}}{3U_1} = \frac{R_2'}{X} OA = BC$$

$$\textcircled{*} P_{elm} = 3 R_2' I_2'^2 \left(\frac{1-g}{g} \right) = 3 R_2' \left(\frac{1-g}{g} \right) \frac{U_1}{X} OA$$

$$\Rightarrow \frac{P_{elm}}{3U_1} = \frac{R_2' (1-g)}{gX} OA = CM$$

$$\textcircled{*} BM = BC + CM = \frac{R_2'}{gX} OA$$

$$BC = \frac{R_2'}{X} OA$$

$$\Rightarrow g = \frac{BC}{BM}$$